

Report NO. SA202406074

TEST REPORT

(1) Sample information

Sample
Description

DMA84 Elevating side platform

Model:

DMA84

Size

/

Quantity

1

Manufacturer Name

Sunon Technology Co., Ltd.

Sample
Category

finished product

Material No.

/

Batch No

/

Entrusting Dep

R&D 1

Entrusting
Date


2024-06-11

Sample(s)
condition

Intact

(2) Testing information

Test Category: Internal Test Test time: 2024-06-12

No.	Test Item	Test Basis	Specification	Test Result	Conclusion
1	1Concentrate functional loads	test basis: ANSI/BIFMA X5.5-2021 	There shall be no loss of serviceability	91kg kept for 60 minutes to meet the requirements	Pass
2	Uniform distribution of functional loads		There shall be no loss of serviceability	122kg loading for 60 minutes meets the requirements	Pass
3	Concentrate the verification load		There shall be no sudden and major change in the structural in tegrity of the product. Loss of serviceability is acceptable.	136kg kept for 15 minutes to meet the requirements	Pass
4	Uniform distribution of verification loads		There shall be no sudden and major change in the structural in tegrity of the product. Loss of serviceability is acceptable.	186kg loading for 15 min Meets the requirements	Pass

(3) Test Result

☒ PASS ☐ FAILED ☐ faithful representation

(4) Remarks

/

Prepare:

黄川

Audit:

李悦

Approve:

罗影

Date:

2024/6/13

Date:

2024/6/13

Date:

2024/6/13

Attached page



----- End of report -----

1. The test result is only responsible for the incoming sample and is related to the tested sample;
 2. If you have any objections to the report, you can apply for reinspection within 15 days after the report is issued;
 3. This report may not be partially reproduced without the written approval of the Center.
- Furniture and Material Testing Center of SUNON Technology Co., Ltd
Building 6, No. 1666, Zhixing Road, Qiaonan Block, Xiaoshan Economic and Technological Development Zone,
Xiaoshan District, Hangzhou City, Zhejiang Province